

From: [Bryant Smalley](#)
To: [Roy Varnado](#)
Cc: [Ray Clement](#); [Rhonda McCormick](#); [Greg Fife](#)
Subject: Re: Southwest Rice Mill incident update 6/21/11
Date: 06/21/2011 09:26 AM

Roy - Thank you for the update. I will notify EQ about the plywood and make sure it is picked up.

Respectfully,

Bryant Smalley
Prevention & Response Branch
Superfund Division
EPA Region 6
214-665-7368

▼ Roy Varnado ---06/21/2011 09:15:52 AM---The area received approximately 0.1-0.2 inches of rain yesterday. The ground was damp, but there we

From: Roy Varnado <Roy.Varnado@LA.GOV>
To: Bryant Smalley/R6/USEPA/US@EPA
Cc: Ray Clement <Ray.Clement@LA.GOV>, Rhonda McCormick <Rhonda.McCormick@LA.GOV>
Date: 06/21/2011 09:15 AM
Subject: Southwest Rice Mill incident update 6/21/11

The area received approximately 0.1-0.2 inches of rain yesterday. The ground was damp, but there were no standing water in the ditch next to the tank area. No sheens were noted in the water and all absorbent booms did not indicate any oil staining. There is a fair amount of skum flowing westward beneath the Roller road bridge.

They are predicting 1-3 inches of rain over the next several days. I will continue to monitor.

I did notice that the contractors left behind the sheets of plywood used at Roller road bridge. When the contractors come to pick up the booms at the end of the monitoring phase, please ask them to pick up the plywood also.



9637159